



## 1968 Vacuum Routing

By 1968 the number of complicated accessories as well as other changes meant that there were allot more processes controlled and operated by vacuum. As a result the number of vacuum lines multiplied. What follows are diagram's showing the routing and connections taken from a number of Ford documents and publications.







